

HISTORIC AMERICAN ENGINEERING RECORD

INDEX TO PHOTOGRAPHS

F. & H. BENNING COMPANY OYSTER MILL

HAER MD-135

14430 Solomons Island Road (moved from 1014 Benning Road,
Galesville, Anne Arundel County, Maryland)

Solomons

Calvert County

Maryland

INDEX TO BLACK AND WHITE PHOTOGRAPHS

Todd A Croteau, photographer, 2005

- | | |
|----------|---|
| MD-135-1 | INTERIOR VIEW WITH GRINDING MILL AND CONVEYOR EXTENDING UP TO SORTING DRUM. DRIVE ENGINE AT LOWER LEFT. RADIATOR FOR ENGINE AT RIGHT. |
| MD-135-2 | SAME VIEW, BUT HORIZONTAL. |
| MD-135-3 | VIEW IN OPPOSITE DIRECTION AS MD-135-1 AND MD-135-2. RAW MATERIAL CONVEYOR AT LEFT DEPOSITS SHELL INTO MILLING MACHINE AT LOWER LEFT. ENGINE IS AT LOWER RIGHT AND RADIATOR AT LOWER CENTER. ROLLER SORTER IS AT TOP OF CONVEYOR. |
| MD-135-4 | VIEW ALONG RAW MATERIAL CONVEYOR AT RIGHT WITH CRUSHED SHELL CONVEYOR ABOVE. ENGINE AND RADIATOR AT LOWER LEFT. |
| MD-135-5 | DETAIL OF SPARE CONICAL CRUSHER AND GRINDING BURR WHEELS REMOVED FROM THE MILLING MACHINE. |